



Stellar Type 1 Service Obsolescence

Discontinuation of Stellar Type 1 Service Capability

Month/Year: December 2017
Date of implementation: December 31st, 2017

Background and History

The Stellar 100™ and Stellar 150™ Type 1 platform (Item codes 24147 and 24156) were launched by ResMed in 2011 and were quickly replaced by the enhanced Stellar 150 Type 2 device (Item code 24162) in 2013.

The Type 1 devices were obsoleted from sale in the region at the end of 2012. ResMed has maintained the serviceability of these items through the 5 year end of support requirements. ResMed will be discontinuing availability of some of the spare parts required to service the Type 1 devices (listed below). Parts not listed below that are backwards compatible between Type 1 and Type 2 devices may be utilised for service.



Our plan to manage service and where applicable, transition partner and patient owned product to the Type 2 platform will involve actively promoting and encouraging the transition from the Stellar Type 1 device variants to the Stellar 150 Type 2 platform. If you would like to discuss your upgrade options, please contact your local ResMed Respiratory Care Business Manager.

Spare Part (Type 1)	Item Code
Main PCB - Stellar 100	19518
MAIN PCB - Stellar 150	19524
Sensor Tubing	19522
Cable Harness	19538
Dial PCB	19541
Interface PCB Assembly	19542

For further information, please contact your local ResMed Respiratory Care Business Manager.