

Stellar Type 1 replacement main PCB obsolescence

Details

The following Type 1 replacement main PCBs for Stellar devices are no longer available:

- #19524 – Stellar 150 (Type 1) main PCB
- #19518 – Stellar 100 (Type 1) main PCB

Where a Type 1 Stellar device (100 or 150) is returned for servicing and requires a main PCB replacement, indicate to the customer that the purchase of a new Stellar device is recommended.

Note: *Service support for the Type 1 Stellar finishes at the end of 2017.*

For appropriate product pricing in response to this issue, consult with your local commercial managers or:

- Davide Nocentini (EMEA-JPN region)
- Gordon Danton (Asia Growth Market)